

KYOCERA® FS-1000

EASY TO REMANUFACTURE CARTRIDGE INSTRUCTIONS



KYOCERA FS-1000 TONER CARTRIDGE

REMANUFACTURING THE KYOCERA FS-1000 TONER CARTRIDGE

By Mike Josiah and the Technical Staff at UniNet



The Kyocera FS-1000 cartridges are rated for 6,000 pages.

The OEM part number is TK-17.

There is NOT a chip used on this cartridge.



1. Remove the fill plug using a small jeweler's screwdriver.

Clean out all the remaining toner.



2. Make sure the toner port is closed, by turning the end screw using a slotted screwdriver.



3. Fill the cartridge with toner for use in the TK-17 series of cartridges. Replace the fill plug.



4. If shipping the cartridge, place a small strip of tape across the toner port.